

April 29, 2024

Representative Michael Guest 3rd District of Mississippi 450 Cannon House Office Building Washington, DC 20515

Dear Congressman Guest,

I am writing to express American Industrial Transport support of the proposed Industrial Park Road Improvement project in the Brookhaven Industrial Park.

Our operations include 21 acres at 113 Boyce Drive and 19 acres at the 516 N. Park Drive address. We currently employ over 75 individuals, with plans to continue growth to well over 100 employees. We also support many supplies and customers all over the county by maintaining logistical assets for dozens of companies. Without robust industrial infrastructure we simply could not operate.

Thank you for your support of Southwest Mississippi and your support of the Industrial Park Road Improvement project in Brookhaven. If you need more information regarding AITX or our operations, please do not hesitate to contact me.

Sincerely, Steve West Director Tank Car, Bude/Brookhaven 516 N. Park Drive Brookhaven, MS 39601 Cell: 478-232-0214

> AITX Railcar Services, LLC 516 North Park Drive Brookhaven, MS 39601

DRY ICE

1423 E RICHEY ROAD, HOUSTON, TX 77073 PHONE: 346-396-7720 / FAX: 515-717-7400 EMORYDRYICE.COM

April 26, 2024

Representative Michael Guest 3rd District of Mississippi 450 Cannon House Office Building Washington, DC 20515

Dear Congressman Guest,

I am writing to express Emory Dry Ice's support of the proposed Industrial Park Road Improvement project in the Brookhaven Industrial Park. Our company recently opened a 20,000 square foot manufacturing facility in the Brookhaven Industrial Park. Our plans are to call Brookhaven home for many years; in order for us to do so, we must invest in the park's public infrastructure.

Our operation employs approximately 20 individuals and supports families from all over the region. We began operations in 2023 and look to continue our growth in Brookhaven.

Thank you for your support of Southwest Mississippi and your support of the Industrial Park Road Improvement project in Brookhaven. If you need more information regarding Emory Dry Ice in Brookhaven or our operations, please do not hesitate to contact me.

Sincerely,

Josh Muno

Josh Russo | EVP Business Development / Founder Mobile: (515) 729-3280 www.emorydryice.com

Headquarters: 1423 E Richey Rd Houston, TX 77073 2046 East Manufacturers Blvd Brookhaven, MS 39601



230 S. Whitworth Ave. • Brookhaven, MS 39601 • P.O. Box 978 (39602-0978)

601-833-1411 • brookhavenchamber.org • 1.800.613.4667

March 26, 2024

Representative Michael Guest 3rd District of Mississippi 450 Cannon House Office Building Washington, DC 20515

Dear Congressman Guest,

I am writing to express my strong endorsement for the proposed Industrial Park Road Improvements within our community. As the Executive Director of the Brookhaven-Lincoln County Alliance, an organization dedicated to fostering economic development projects, I am keenly aware of the transformative impact that such infrastructure enhancements can have on our region's prosperity.

The Industrial Park Road Improvements are essential for advancing our economic development goals and attracting investment to our community. By enhancing transportation networks and improving access to our industrial park, we are creating an environment conducive to business growth and expansion. These improvements will not only facilitate the movement of goods and services but also position our community as a competitive destination for businesses seeking strategic locations with efficient infrastructure.

Furthermore, these road enhancements align with our broader mission of promoting sustainable economic development and enhancing the quality of life for our residents. By reducing traffic congestion and improving safety, we are creating safer and more accessible pathways for both businesses and residents. This, in turn, fosters a sense of community pride and strengthens the overall fabric of our region.

I commend the collaborative efforts of all stakeholders involved in advocating for these important improvements. Their dedication to advancing our community's economic vitality is truly commendable. As Executive Director of the Brookhaven-Lincoln County Alliance, I offer my full support for the Industrial Park Road Improvements and stand ready to assist in any way possible to ensure their successful implementation.

Thank you for considering this letter of support. Should you require any further information or collaboration, please do not hesitate to contact me directly.

Sincerely.

Garrick Combs, Executive Director Brookhaven-Lincoln County Economic Development Alliance P. O. BOX 560

CITY OF BROOKHAVEN, MISSISSIPPI "HOMESEEKERS' PARADISE"

ZIP 39602-0560

ALDERMEN DON UNDERWOOD JAMES MAGEE, JR SHANNON MOORE CHARLES J, CASTON, SR JEFF HENNING FLETCHER GRICE ANDRE' D. SPILLER

March 26, 2024

Representative Michael Guest 3rd District of Mississippi 450 Cannon House Office Building Washington, DC 20515

Dear Congressman Guest,

JOE COX, MAYOR KENNETH COLLINS, CHIEF OF POLICE SAMATHA MELANCON, CITY CLERK

I am writing to express my wholehearted support for the proposed Industrial Park Road Improvements in our city. These enhancements are crucial for the continued growth and prosperity of Brookhaven, and I am confident that they will yield significant benefits for our community and its residents.

Improving the infrastructure surrounding our industrial park is essential for attracting new businesses, encouraging investment, and facilitating the movement of goods and services. As our city continues to evolve and expand, it is imperative that we have modern, efficient transportation networks in place to support our economic development goals.

The proposed road improvements will not only enhance connectivity within our industrial park but also improve access to major transportation routes, such as Interstate 55 and Highway 84 thereby increasing the efficiency of freight movement and reducing congestion. Moreover, these upgrades will make our city more attractive to businesses seeking locations with reliable infrastructure and logistical advantages.

In addition to the economic benefits, these improvements will also have positive impacts on our community's quality of life. By reducing traffic congestion and improving safety, we will create a more livable and sustainable environment for our residents. Furthermore, the resulting economic growth will generate new job opportunities and stimulate local businesses, fostering a stronger and more vibrant community.

I commend the efforts of all those involved in planning and advocating for these much-needed improvements. We look forward to partnering with The Lincoln County Board of Supervisors to make this project a success. Their dedication and hard work reflect our shared commitment to the prosperity and well-being of Brookhaven. As Mayor, I am proud to offer my full support for this project and look forward to seeing its successful implementation for the benefit of our city and its residents.

Thank you for considering this letter of support. Please do not hesitate to contact my office if you require any further information or assistance regarding this matter.

Sincerely.

Joe C. Cox, Mayor of Brookhaven

Lincoln County Board of Supervisors

Lincoln County Mississippi P.O. Box 555 • 301 South First Street • Brookhaven, Mississippi 39602-0555 Telephone 601/835-3421 • Fax 601/835-3423

Board of Supervisors Dist. 1 Jerry Wilson Dist. 2 Keith Lewis Dist. 3 John Hart Dist. 4 Ell Ferguson Dist. 5 Doug Falvey

Chancery Clerk Alisha McGehee Board Attorney F. Gregory Malta County Administrator Daniel Calcote

March 26, 2024

Representative Michael Guest 3rd District of Mississippi 450 Cannon House Office Building Washington, DC 20515

Dear Congressman Guest,

I am writing to convey my enthusiastic support for the proposed Industrial Park Road Improvements within Lincoln County. As President of the Board of Supervisors, I recognize the significant positive impact that these enhancements will have on our county's economic development and overall prosperity.

The Industrial Park Road Improvements represent a critical investment in our county's infrastructure. By modernizing and expanding our transportation networks, we are positioning Lincoln County as an attractive destination for businesses looking to establish or expand their operations. Improved access to our industrial park will not only facilitate the movement of goods and services but also enhance the efficiency of our local economy.

Furthermore, these road enhancements will contribute to the safety and well-being of our residents. By reducing traffic congestion and enhancing connectivity, we are creating a safer environment for motorists and pedestrians alike. This is essential for fostering a thriving community where residents feel secure and supported.

I commend the collaborative efforts by the City of Brookhaven in advancing this important project. Their dedication and vision are instrumental in shaping the future success of Lincoln County. As President of the Board of Supervisors, I am proud to offer my full endorsement for these Industrial Park Road Improvements and stand ready to support their implementation in any way possible.

Thank you for considering this letter of support. Should you require any further information or assistance, please do not hesitate to reach out to my office.

Sincerely, Soug Falver

President of the Board of Supervisors Lincoln County

Harry Lee James, P.E. State Aid Engineer P.O. Box 1850 Jackson, Mississippi 39215 Phone (601) 359-7150



112 E. Woodrow Wilson Ave. Jackson, Mississippi 30216 Fax (601) 359-7141 www.osarc.ms.gov mail@osarc.ms.gov

May 5, 2023

Board of Supervisors Lincoln County c/o Chancery Clerk Post Office Box 555 Brookhaven, MS 39601

> RE: Annual Maintenance Inspection of Completed State Aid Road and Bridge Projects Lincoln County

Gentlemen,

Attached is the report of the Annual Maintenance Inspection, which was conducted on April 19 & 26, 2023. The report lists many items of work to be done. Your prompt attention to those items will be appreciated.

Surfaces were generally in good condition except where noted for a surface treatment. Most shoulders need to be clipped back to allow water to drain from pavements. There are various signs around the county that need replacing or straightening. Some projects need to the ditches cleaned to allow water to drain properly.

You gentlemen are commended for your efforts to maintain Lincoln County's State Aid projects and urged to continue to keep your State Aid Projects in satisfactory condition.

Sincerely,

Harry Lee James, P.E. State Aid Engineer Chris D. Dixon, P.E. By District Engineer

CDD

Attachment

pc: Mr. Jerry Wilson Mr. Jerry McGehee Mr. Nolan Williamson Mr. Eddie Brown Mr. Doug Falvey Mr. Ryan Holmes File



MAINTENANCE INSPECTION REPORT

OFFICE OF STATE AID ROAD CONSTRUCTION MISSISSIPPI DEPARTMENT OF TRANSPORTATION

Lincoln County

DATE OF THE INSPECTION: April 19 & 26, 2023

Chris D. Dixon, P.E., State Aid District Engineer Ryan Holmes P.E., County Engineer, Dungan Engineering

Surfaces and shoulders are in reasonably good condition on most projects except where noted for maintenance. Shoulders need blading off or building up where noted. Drainage structures were mostly satisfactory except where noted for painting or extending encasements or piling replacement. Rights-of-way need to be cut farther back on some projects. Signs and striping need replacing on some projects. Some projects need the ditches to be cleaned to allow drainage. Please refer to the NBI inspection reports for any maintenance required on bridges.

A. Items which need to be corrected immediately:

۱.

Maintenance items which need to be corrected as soon as practicable: B.

Districts 1 & 3

1

Mallalieu Road SAP-43(7), 43(8), 43(75), DS-1203(1)B, S-1203(2)B, SAP-43(6)M North portion of (75) Micro-surfaced in 2013 (7) – Reseal 2020 S-1203(4)B – Resealed 2022 Remove vegetation from signs Depleae mission object markers Replace missing object markers Straighten signs and object markers Build up areas of low shoulders S-1203(2)B -Recommend surface treatment Level areas of rutting. Shoulders need clipping in areas Repair base failures

Brookhaven - Monticello Road (East Lincoln Road) S-175-2(1), SAP-43(72), S-175-2(2), S-0175(3)B, ER-0175(5)B, SAP-43(77), (5)M, (6)M Micro surfaced 2013 (US 84 to Bethel Rd) S-0175(2)2 - resealed 2022 Recommend surface treatment Repair damaged guard rails. Remove brick and other hazardous mailboxes from 10' clear zone. Build up areas of low shoulders Repair base failures Straighten signs and object markers Replace missing object markers S-0175(2)2 - Remove trees and vegetation from bridge and guard rail S-0175(3)B – Needs striping

Recommend surface treatment

District 1

<u>Camerons Store - East Lincoln Road</u> SAP-43(46) Resealed 2020

East Lincoln - Fair Oak Springs Road (Harmony Church Road) S-244-2(1), S-244-2(2), ER-0244(4)B, BR-0043(15)B, SAP-43(10) Resealed 2020 Repair damaged guardrail at bridge. Shoulders need clipping in areas. Build up areas of low shoulders Remove vegetation from bridges Mow around and under guard rails

Dickerson Road LSBP-43(18) Mow behind guard rails

Kinder Trail LSBP-43(23) Mow behind guardrail

District 1 & 3

÷

Union Church Road BR-0043(21)BO, LSBP-43(13) BR - Resealed 2021

District 1

Ailen Road LSBP-43(2), (47) Replace old and missing object markers. Remove vegetation from bridge

Nations Road LSBP-43(18) Mow behind and under guardrails.

Zude Russell Road LSBP-43(13) Maintenance is satisfactory.

Gill Drive LSBP-43(9) Replace missing object markers.

Harmony Church Road (Pleasant Grove Road) SAP-43(43) Resealed 2020 Replace missing object marker

District 1 & 3

East Lincoln - Topeka Road (China Grove Road) SAP-43(44), (65) Repair base failures. Recommend surface treatment

County Farm Road SOS-0043(7)B, SAP-43(88) Needs striping. Recommend surface treatment. Shoulders need clipping in areas Repair pavement edge drop-offs and areas of low shoulders Replace missing object markers Repair base failures Repair damaged shoulders

<u>Pleasant Grove Road</u> LSBP-43(31) Replace missing object markers. Remove fence from ROW

<u>Greenwood Road</u> LSBP-43(3) Replace missing object markers

District 2

.

Union Hall - Lawrence County Line Road (Nola Road) SAP-43(12), S-0174(2)B

SAP-43(12), S-0174(2)B
(12) - Micro surface in 2013
S-0174(2)B - Resealed 2021
(12) - Replace missing and damaged object markers

Repair base failures

Mow behind guardrails
Build up areas of low shoulders
Shoulders need clipping in areas

Acy Trail LSBP-43(14) Maintenance is satisfactory

<u>Autrey Lane</u> LSBP-43(1) Maintenance is satisfactory.

International-Pipeline Road BR-0043(26)BO

BR-0043(26)BO Straighten signs Level pavement at box. Recommend surface treatment

Cotton Lane LSBP-43(41)

Maintenance is satisfactory

Sandifer Lane LSBP-43(14) Maintenance is satisfactory.

District 1&2

Union Hall - Lawrence County Line Road (Nola Road) SAP-43(24) Resealed 2021 Replace old, damaged and missing signs and object markers. Replace missing large arrow at Nalco Road Remove hazardous mailbox from 10' clear zone Shoulders need clipping in areas Mow behind guard rails

District 2

Hueck's Retreat - Tyrus Road SAP-43(3), 43(58), BR-0173(1)B, STP-0173(5)B SAP-43(3), (58) - Micro surfaced 2013 Recommend surface treatment Straighten signs and object markers Needs striping Repair base failures Replace missing and damaged signs and object markers Shoulders need clipping in areas

Beard (Mound) Road LSBP-43(7)

Remove vegetation from bridge. Remove graffiti from bridge Replace missing object marker

Bahalia Road SAP-43(9), (1)M

Repair base failures Replace missing object markers Repair wash at wing wall

Little Bahalia - Wesson Road (Mission Hill Road) SAP-43(6) Micro surfaced 2013 Replace missing chevrons in curve. Replace vandalized & damaged signs Replace missing object markers Repair base failures Repair broken pavement edges Remove vegetation from signs Needs striping

District 2 & 5

Beltline Road (and Industrial Park) SAP-43(14), (32), (86), (2)M, STP-9517(1)B Phases I, II, III, & IV Recommend surface treatment on SAP-43(32). Re-stripe surface on SAP-43(32). STP-9517(1)B - Recommend surface treatment Remove vegetation from bridge Puilder Build up areas of low shoulders

District 2

Smith Lake Road LSBP-43(16) Maintenance is satisfactory.

New Sight Road SAP-43(17), (34)

(17) Micro surfaced 2013 Remove hazardous mailboxes. Shoulders need clipping in areas. Replace old and damaged signs and object markers Needs striping Repair base failures Replace missing object markers Recommend surface teatment

Mount Zion - U.S. #51 Road (Lott Smith Road and Faye Lane)

SAP-43(23), SAP-43(9) Replace old, damaged and missing object markers and signs. Straighten signs Recommend surface treatment Needs striping Level areas of rutting Repair base failures Shoulders need clipping in areas (9) - Repair pavement at bridge ends

St. John Road SAP-43(79)

Remove hazardous mailbox. Resealed 2020 Shoulders need clipping in areas

Pearlie Road

LSBP-43(22) Maintenance is satisfactory.

<u>Lake Lincoln Road</u>

SAP-43(45) Repair wheel rutting. Repair base failures Recommend surface treatment Replace missing signs Repair damaged shoulder Shoulder needs clipping in areas Needs striping

Beard Road and Sunset Road SAP-43(50) "A" & "B", SAP-43(84) Sunset Rd. – Level areas of rutting

- Repair base failures
- Replace missing object markers
- Recommend surface treatment
- Shoulders need clipping in areas
- Beard Rd Level areas of rutting
 - Repair base failures
 - Shoulders need clipping in areas

Fair River - Little Byhalia Road SAP-43(37)

Shoulders need clipping in areas Repair base failures Recommend surface treatment Build up areas of low shoulders Remove vegetation from bridge and clean bridge deck

Hopewell Road LSBP-43(33) Remove graffiti Replace missing object markers Clean bridge deck Cut back tree growth

Old U.S. Highway #51 SAP-43(53), (36)

Micro surfaced in 2013 Remove fences off Right-of-Way. Straighten signs and object markers. Replace missing object markers Recommend surface treatment Remove vegetation from bridge Shoulders need clipping in areas Build up areas of low shoulders Clean out ditches Recommend surface treatment Repair damaged bridge rail

Forest trail LSBP 43(6), (31) (6) – replace old object markers. (31) – Replace missing object marker

Field Lark Lane LSBP-43(29)

Maintenance is satisfactory.

Belt Line Road, south of curve SAP-43(64), 43(80) Resealed 2020 Build up low shoulders. Repair pavement edge drop offs

District 3

<u>Wellman Church - East Lincoln Road (Wellman Road)</u> SAP-43(28)

Needs striping. Replace damaged and missing signs Pavement needs leveling in areas

Russ Anna Lane LSBP-43(29)

Cut back vegetation. Locked out.

Enterprise - Norfield Road SAP-43(29), (21)S Microsurfaced 2016 Shoulders need clipping in areas

.

Enterprise -Wellman - Ruth Road (Topisaw Road) SAP-43(4) Micro surfaced 2016 Repair base failures Straighten signs Needs striping Recommend surface treatment

Bogue Chitto - Ruth Road S-0176(1)B, BR-0176(4)B Resealed 2021

Build up areas of low shoulders

Shady Grove - Pleasant Hill Road ER-1273(1)B

Resealed 2021

Fox Road

SAP-43(33), (42) Needs striping Clean bridge deck

Dixon Creek Road LSBP-43(7)

Repair damaged bridge rail.

Park Hill Road LSBP 43(11) Maintenance is satisfactory

Mt. Pleasant Road

LSBP-43(19), (42) Maintenance is satisfactory

Pleasant Hill Road LSBP-43(49) Maintenance is satisfactory

Districts 3 & 4

Bogie Chitto - Northwest Road (Calvary Road) SAP-43(20) Paint bridgé steel - under maintenance project. Needs striping Shoulders need clipping in areas

District 3

Cole Road LSBP-43(3) Clean bridge deck

Topisaw Church Road BR-0043(24)B Needs striping Recommend surface treatment

Reeves Road

LSBP-43(5) Replace missing object markers

Ruth - Felders Campground Road SAP-43(47) Resealed 2020 Straighten object markers

.

Blueberry Hill - Pike County Line Road (Pricedale Road) SAP-43(56) Resealed 2021

Moaks Creek Road

LSBP-43(1), (37) Maintenance is satisfactory.

Windmill Road LSBP-43(2) Satisfactory Maintenance.

South First Street (Old U.S. Highway #51) SAP-43(69)

Micro surfaced 2013 Recommend surface treatment Needs striping Repair base failures

Greenview Trail LSBP-43(32) Maintenance is satisfactory.

Dale Trail LSBP-43(1)

Cut R/W back Remove vegetation from bridge.

Upton Trail LSBP-43(19) Maintenance is satisfactory.

Carpenter Lane LSBP-43(25)

Remove fence from ROW.

River Road (Hog Chain Road) SAP-43(52) Replace old signs and object markers. Needs striping Repair base failures Recommend surface treatment

Pricedale Road (River Road) 43(70), (74), BR-0043(18)B Resealed 2021

Somerset Road LSBP 43(11)

Maintenance is satisfactory.

District 4

Lower Meadville Rd. LSBP-43(17)

Maintenance is satisfactory

Auburn Road SAP-43(27), S-0167(3)B, SAP-43(35), 43(1)M, SAP-43(6)M, BR-0043(25)B Replace old and missing signs and object markers Consider adding chevrons at curve. Stripe north of chip mill - Recommend surface treatment. Straighten signs Shoulders need clipping in areas Repair base failures. Repair shoulder at mill. Build up areas of low shoulders Pavement needs leveling in areas Recommend surface treatment Needs striping

Jackson - Liberty Road S-167-2(1), RS-0167(15)B, S-167(2)2, SR-0043(14)B, STP-0119(19)B, BR-0119(20)B STP-0119(19)B - Resealed 2020 Remove hazardous mailbox. Replace guardrail Recommend surface treatment Needs striping Repair base failures and potholes Build up areas of low shoulders Mow around and under guardrails

West Lincoln Road

SAP-43(83) Recommend surface treatment Repair base failures Shoulders need clipping in areas Remove vegetation from signs Replace vandalized signs

<u>Arlington - Summit Road</u> S-1180(1)B

Micro surfaced 2013 Replace missing object markers Shoulders need clipping in areas Repair base failures Recommend surface treatment Straighten signs Needs striping

Gene Road

LSBP-43(28) Maintenance is satisfactory

Stancil Road LSBP-43(28)

Cut back trees and vegetation, both sites

Shar- Pei Lane LSBP-43(17) Cut back trees

Big Creek Road LSBP-43(34)

Remove graffiti from bridge Replace missing object markers Cut back trees

Beechnut Trial

LSBP-43(47) Maintenance is satisfactory

Montgomery Church Road SAP-43(89)

Resealed 2021 Shoulders need clipping in areas Replace missing object markers Straighten signs

Freeman Road LSBP-43(4)

Replace missing object markers

Dry Creek Road

LSBP-43(7) Maintenance is satisfactory.

<u>Chestnut Lane</u> LSBP-43(49)

Maintenance is satisfactory.

Arlington Road S-1180(2)B

Repair upstream apron at box. Repair base failures Shoulders need clipping in areas Recommend surface treatment Needs striping

Bogue Chitto - Arlington Road RS-0176(2)B, SAP-43(2)M, 43(78), SAP 43(39), (14)M Resealed 2021 Repair downstream apron at box. Consider adding rumble strips at intersection of Jackson Liberty Road Shoulders need clipping in areas Build up areas of low shoulders Clean bridge deck (39) - Recommend surface treatment - Repair base failures

- Replace missing object markers

Jackson - Liberty Road (North of Auburn Road) S-0243(3)B, 43(54), (55), SAP-43(5)M Micro surfaced 2013 (to West Lincoln) Resealed south of W. Lincoln Road 2020 Recommend surface treatment (Scrub Seal?) north of West Lincoln Rd Needs striping north of West Lincoln Rd. Repair base failures and potholes in pavement Replace missing object markers

Jordan Road LSBP-43(9), (12) Cut back trees and vegetation.

Fern Lane LSBP-43(28) Maintenance is satisfactory

Rollins Road LSBP-43(46) Maintenance is satisfactory

Brookway Boulevard RS-2158(1)B Resealed 2020 Remove hazardous mailboxes.

Farver Road LSBP-43(39) Maintenance is satisfactory

Districts 4&5

.

Zetus Road S-0170(1)B, (2)B, SG-0170(3), BR-1199(2)B Micro surfaced 2013 Paint steel piling and girders at bridge. Remove hazardous mailboxes. Repair base failures Repair caution lights at Brookway Boulevard Recommend surface treatment Needs striping Clean bridge deck BR-1199(2)B - Resealed 2020 - Repair base failures

District 5

Jackson - Liberty Road S-243-2(1), SAP-43(67)"A", S-0243-2(2), SAP-43(1), (51) Recommend surface treatment. Repair base failures Straighten signs Build up areas of low shoulders

Russell Lane ISBP 43(6) Replace missing and old object mar

Replace missing and old object markers

Wakefield Road LSBP 43(47) Clean deck

•

Posey Road SAP-43(26), (66) Replace missing object markers Shoulders need clipping in areas Repair base failures Needs striping

Old Jackson Road SAP-43(21), SAP-43(4)M, STP-2183(1)B (21) - Micro surfaced 2013

- Repair base failures Paint steel piling at bridge. STP-2163(1)B - Needs striping Recommend surface treatment.

California Road BR-0043(29)B

Recommend surface treatment / seal cracks

<u>Apaloosa Lane and Palomino Loop</u> LSBP-43(40) Maintenance in satisfactory

Author Drive LSBP-43(8), LSBP-43(36) Maintenance is satisfactory

Durr Case Road LSBP-43(36) Maintenance is satisfactory

<u>Macedonia Road</u> SAP-43(30) Recommend surface treatment Shoulders need clipping in areas

Callendar - Saxton Road (Allred Road and Mormon Trail) S-1201(1)B Resealed 2021 Repair low and damaged shoulders

Tampa Trail LSBP-43(20)

Maintenance is satisfactory.

Saxton - Caseyville Road S-1200(1)B, SAP-43(48) Resealed 2021 Repair low and damaged shoulders Shoulders need clipping in areas Replace missing object markers

1 e

Caseyville Road (Homochitto Road) ER-83(1)B, ER-0275(11)B, BR-0275(13)B, PLH-0275(16)B

Repair base failures Replace old and missing signs and object markers Needs striping Straighten signs Clean gutters Recommend surface treatment Clean bridge decks Build up areas of low and damaged shoulders

Pioneer Trail LSBP-43(25)

Cut back trees Clean deck

Denon Scott - Caseyville Road (Bouie Mill Road) SAP-43(11), (19)

Replace damaged, old and missing signs and object markers Remove hazardous mailbox from clear zone. Needs striping Recommend surface treatment Repair base failures Shoulders need clipping in areas Clean deck

Falvey Road LSBP-43(5)

Remove vegetation from bridge

Pleasant Ridge Road LSBP-43(51) Under construction

Harvey Drive LSBP-43(10), LSBP-43(36) Maintenance is satisfactory

Dunn - Ratliff Road SAP-43(85), Resealed 2020 Repair base failures Surface needs leveling in areas

Old Red Star Road (Union Street Extension) SAP-43(13), (67)"B"

Paint steel piling and structural steel on bridge. Needs striping

Old Red Star Road SAP-43(71), RS-0172(3)B, RS-2164(1)B, SAP-43(6)M, SAP-43(41), SAP-43(49) Resealed 2020

Chris D. Dixon, P.E. By: District Engineer



March 26, 2024

Representative Michael Guest ^{3rd} District of Mississippi 450 Cannon House Office Building Washington, DC 20515

Dear Congressman Guest,

I am writing to express Rex Lumber's support for the proposed Industrial Park Road Improvement project in the Brookhaven Industrial Park. The proposed project will ensure that the raw materials and finished products of Rex Lumber can continue to be efficiently transported to connecting federal highways.

Rex Lumber would like to express its strong endorsement of this project, including any assistance that your office can provide to the community. Rex Lumber manages dozens of trucks per day that support over 170 direct employees and their families in Southwest Mississippi. Without carefully maintained roads serving our Brookhaven facility, we simply cannot operate.

Our company appreciates your service to our community and our country. We are also thankful that you understand and appreciate the need to continue to invest in the vital infrastructure that supports the thousands of jobs and dozens of companies that call the Brookhaven Industrial Park home.

Should you need further information regarding Rex Lumber or our operations, please do not hesitate to contact me.

Graceville 850.263,2056

Bristol 850.643.2238

Brookhaven

Corporate 850.263.4457 Sincerely,

Mul. Ahe

Mark Isbell General Manager Rex Lumber Brookhaven

Post Office Box 7 ' Graceville, Florida 32440

REX-LUMBER.COM



April 29, 2024

The Honorable Michael Guest United States Congress 450 Cannon House Office Building Washington, DC 20515

Subject: FY 2025 Congressionally Directed Spending Industrial Road Improvements, Lincoln County, Mississippi

Dear Congressman Guest:

The Mississippi Department of Transportation (MDOT) has reviewed Lincoln County's FY 2025 Congressionally Directed Spending proposal to upgrade roads and access to the industrial park. This letter is to confirm:

- 1. The project is eligible for federal-aid highway funding under title 23, United States Code;
- 2. MDOT is willing to provide oversight of the project, carried out by an eligible local public agency, in accordance with federal regulations if funding is enacted; and
- 3. The project will be included in the STIP if funding is enacted.

Thank you for your consideration of this project and please feel free to contact me if you have any questions.

Sincerely,

What

Brad White Executive Director